	ings too	•	
		0&T 55-797	
	Chief, Engineering Division, OC	,	
		1.9 000	
	Chief, Operations and Training Division, OC	Chief, Operations and Training Division, OC	
	Manufacture of Transmitter Adaptor		
	The state of the s	PLEASE RETURN TO RAID LAB	
		PLEASE RETURN TO	
		,	
		· .	
	1. The attached Adaptor h	aa baan damanustuustu a	
	to the interested operating Divisions. A firm	as been demonstrated requirement has	
	been established for 15 of these units.		
	2. The following modifications are to be	made, in addition	
	to those modifications which were recommended laboratory analysis and appraisal of this unit	on page 12 of your	
	to those modifications which were recommended	on page 12 of your	
	to those modifications which were recommended laboratory analysis and appraisal of this unit a. The antenna input should be place	on page 12 of your  ed in a more  d further apart.	
	a. The antenna input should be plac accessible location.  b. The headphone jacks must be moved at present the pin type plugs short together with the pin type plugs short toge	on page 12 of your  define a more  defurther apart.  hen placed in the	
	a. The antenna input should be place accessible location.  b. The headphone jacks must be moved At present the pin type plugs short together wind jacks.  c. The BFO adjust moved from its prefer a crystal has been inserted in the unit.	on page 12 of your  define a more  defurther apart.  hen placed in the	
	a. The antenna input should be place accessible location.  b. The headphone jacks must be moved At present the pin type plugs short together wind jacks.  c. The BFO adjust moved from its prefer a crystal has been inserted in the unit.	on page 12 of your  define a more  defurther apart.  hen placed in the	
	a. The antenna input should be place accessible location.  b. The headphone jacks must be moved At present the pin type plugs short together wind jacks.  c. The BFO adjust moved from its prefer a crystal has been inserted in the unit.	on page 12 of your  define a more  defurther apart.  hen placed in the	
	a. The antenna input should be place accessible location.  b. The headphone jacks must be moved At present the pin type plugs short together wind jacks.  c. The BFO adjust moved from its prefer a crystal has been inserted in the unit.	on page 12 of your  define a more  defurther apart.  hen placed in the	
	a. The antenna input should be place accessible location.  b. The headphone jacks must be moved At present the pin type plugs short together wind jacks.  c. The BFO adjust moved from its present a crystal has been inserted in the unit, difficult to adjust.	on page 12 of your  define a more  defurther apart.  hen placed in the	

Declassified in Part - Sanitized Copy Approved for Release 2012/02/22 : CIA-RDP78-03535A000600040030-7